



Mk II exhaust port section



Ultimately the sharp turn on the port roof restricts flow.

Gas flow work around the valve guide boss can increase flow by 30%. However this makes little noticeable difference on a road car.